

---

## *HCX5000 System and Custom Update List For Release 910*

---

<i>Update</i>	<i>Note</i>	<i>Description</i>	<i>Update Type</i>	<i>Processor</i>
			<i>CUSTOM</i>	<i>16 BIT</i>
9009	N/A	PMS/Hobic format expands sequence number to 4 digits, fixed location for TOC, and STX/ETX/BCC replaced by CR/LF.	<i>CUSTOM</i>	<i>16/32</i>
0001	N/A	Check BCL PUD bit ( pickup display) for cover call to Attendant	<i>CUSTOM</i>	<i>32 BIT</i>
9010	N/A	Expand DNIS text name entries form 30 to 99		

---

**Note 1: This update uses an overlay area which may cause the system to become unstable when some CMAT screens are accessed prior to reload.**

**Note 2: This update modifies the customer data area. RCD must not be performed after this patch is applied until the system is reloaded.**

**Note 3: This update was determined to be deficient after it was released. Please check for a later update to supplement this one.**

<i>Update</i>	<i>Note</i>	<i>Description</i>	<i>Update Type</i>	<i>Processor</i>
			<i>SYSTEM</i>	<i>16/32</i>
0001	N/A	Allow line registration of SS930 on 16DLID (16 port)		
0002	N/A	Fix wrong linkage between 2500 station and VMS line after RNA timeouts when a CWC to VMS is set		
0003	N/A	Fix caller ID mismatch for redirected call		
0004	N/A	Fix cover mode display in idle screen		
0005	N/A	Fix TRKIDDATA&STSLGDAT		
0006	N/A	Correct 120 MEG HDD processing		
0007	N/A	SMDR output may contain garbage characters		
0008	N/A	Remove error checking for line class change		
0009	N/A	Wrong digits sent to VMS after cover all / transfer		
0010	N/A	Fix TS (time slot) lockup of 3 stage switching		
0011	N/A	Fix SS910 line 2 out of service problem after system power-on		
0012	N/A	Suppress errant DWI fault messages		
0013	N/A	Update 40 MEG FMS default numbers		
0014	N/A	Change 16DLIE (32 port) initialization default value from SS900 to SS910		
0015	N/A	Fix CCT status of DLC & DLI in case of package MKB		
0016	N/A	Change number display of SS910 from 10 digits to station number for an internal call		
0017	N/A	Correct CMAT screen 2.1.4.3 "COVER ALL" cancel		
0018	N/A	Send circuit info to 16DLI when SS900 is registered		
0019	N/A	SS910's LCD does not change from default by CCT:MKI		
0020	N/A	Fix TS lockup and PRI trunk idle chain problem		
0021	N/A	Free memory allocation after remote access		
0023	N/A	Fix TS lockup problem in case of Call Waiting		
0024	N/A	Fix TS lockup problem in case of wrong LPN input for tone release (PRI)		
0025	N/A	Require MKB before registering SS910 line		
0026	N/A	Fix TS lockup problem for PRI to ACD all busy delay timeout		
0027	N/A	Correct editing of screen 2.1.2.1., page 4		
0028	N/A	Allow international calls for "REQUIRE 1+ FOR TOLL" system class		
0029	N/A	Changes to support 5100M		
0030	N/A	Correct auto key corruption on pattern mismatch		
0031	N/A	Correct line package checks during line registration		
0032	N/A	Correct SS910 line registration error checking		
0033	N/A	PRI screen 2.1.9.2.27 does not work with NI2 trunk		

**Note 1: This update uses an overlay area which may cause the system to become unstable when some CMAT screens are accessed prior to reload.**

**Note 2: This update modifies the customer data area. RCD must not be performed after this patch is applied until the system is reloaded.**

**Note 3: This update was determined to be deficient after it was released. Please check for a later update to supplement this one.**

<i>Update</i>	<i>Note</i>	<i>Description</i>	<i>Update Type</i>	<i>Processor</i>
0034	N/A	Invalid station from 9-less station causes error restart		
0035	N/A	Department report misses some stations		
0036	N/A	Added TAFAS label to ATT Traffic Report		
0037	N/A	Correct output of 2 digit ACD group to DWI		
0038	N/A	Correct output of first period ACD agent data to DWI		
0039	N/A	Fix variable CMAT F1 error		
0040	N/A	Eliminate PRI L3 protocol error when receiving SHIFT "CODESET 6" information element		
0041	3	Fix variable CMAT 1/2 decision menu error		
0042	N/A	Attendant intraflow cover busy to VMS not sending digits		
0043	N/A	Attendant intraflow station does not cover no answer to VMS		
0044	1	Fix/Enhance ISDN Trace Command		
0045	N/A	Fix PMS memory allocation error in PMS "STE" messages		
0046	N/A	Fix Tertiary Switch time slot lockup after transfer trunk no answer recall		
0047	N/A	Fix PRI L3 protocol error for invalid coding standard in disconnect message		
0048	N/A	Fix PRI L3 protocol error (cause 96) due to improper disconnect sequence		
0049	N/A	Fix occasional problem deleting remote maintenance center in CMAT screen 6.1		
0050	N/A	Fix variable CMAT 1/2 decision menu error part two		
0051	3	Fix intermittent failure when backing up floppies (part 1)		
0052	N/A	Correct "UNKNOWN NAME" cases when calling name sent in PRI facility message		
0053	N/A	Fix intermittent failure when backing up floppies (part 2)		
0054	N/A	Skip SYSLOG when backing up floppy disk number two		
0055	N/A	Correct TGN traffic report incoming talk average calculation		
0056	N/A	Fix PRI L3 protocol error (Cause 96) due to improper disconnect sequence		
0057	N/A	Fix VMS lockup when invalid PRI facility message is sent from CO		
0058	N/A	Fix error restart when automatic callback is interrupted by new call		
0059	N/A	Quiet the squeal on some T1 connections / transfers		
0060	N/A	Fix intermittent timer degradation		
0061	N/A	Fix intermittent failure when backing up floppies (part 3)		
0062	N/A	Fix "UNKNOWN NAME" on CAP 2 call when calling name is sent in PRI FAC message		
0063	N/A	Fix L3 protocol error caused by double connect of ACD greeting		
0064	N/A	Correct fault ID after DWI restart		
0065	N/A	Correct DID error checking on station cancellation		
0066	N/A	Correct operation of wakeup terminating to unplugged SelecSet		

**Note 1: This update uses an overlay area which may cause the system to become unstable when some CMAT screens are accessed prior to reload.**

**Note 2: This update modifies the customer data area. RCD must not be performed after this patch is applied until the system is reloaded.**

**Note 3: This update was determined to be deficient after it was released. Please check for a later update to supplement this one.**

<i>Update</i>	<i>Note</i>	<i>Description</i>	<i>Update Type</i>	<i>Processor</i>
0067	N/A	PRI DID calling name to HGF locks up analog port		
0068	N/A	Prevent system crash after direct trunk access switch hook flash		
0069	N/A	Remove extraneous characters from FOA/SMDR for incoming caller ID		
0070	N/A	Allow immediate retry of floppy backup after FLTID=0252		
0071	N/A	Quiet the squeal on some T1 connections / transfers		
0072	N/A	Quiet additional cases for trunk squeal tones		
0073	N/A	Fix FLTID 0001 system error when receiving PRI sub-minimum length message		
0074	N/A	Restrict (NAK) long invalid PMS messages		
0075	N/A	Correct memory allocation corruption related to PMS flex room suite		
0076	N/A	Correct version-up error on some larger systems		

---

**Note 1: This update uses an overlay area which may cause the system to become unstable when some CMAT screens are accessed prior to reload.**

**Note 2: This update modifies the customer data area. RCD must not be performed after this patch is applied until the system is reloaded.**

**Note 3: This update was determined to be deficient after it was released. Please check for a later update to supplement this one.**